

TECHNICAL DATA

PAC-420

NON-PHOS FOAM ACID CLEANER

Description:

This is a concentrated non-phosphate product containing a blend of acids and detergents. It effectively removes hard water scale, stains and grime build up from concrete, metal surfaces, vinyl, tile, bath tubs, toilets and urinals.

Directions for Use:

Remove oil and grease from surfaces to be cleaned with a proper degreaser. Then apply a solution of 1 part product to 4 parts of water by using a low pressure sprayer, dip, brush or sponge. It is not recommended to be applied with a high pressure washer. Allow solution enough contact time so scale is dissolved or may be removed by rinsing with hot water. Avoid prolonged contact with aluminium and other soft metals. For lighter cleaning jobs, dilute with up to 10 parts of water.

FOR FOOD PLANT & INDUSTRIAL USE ONLY